Technical Assistance: 105 Handbrake calipers – Banjo bolt bleeding problem.

Symptom: Real struggle to tighten banjo bolt and impossible get any fluid out.

Cause: Failure to remove the sealing bung out of the inlet hole. Some handbrake calipers are difficult to bleed; so both the original equipment units and Budweg calipers are vacuum pre-filled with brake fluid to assist installation.

Solution: Kick yourself for not reading the instructions and not inspecting the inlet when the banjo bolt wouldn't screw home properly. Hope that you'll be able to get the crushed bung out and the threads are not damaged.



Note

This is not a manufacturing fault and is not covered under guarantee.

